# CUSTOM®

| Software Code: SC000000000104 | Product family:  Kubell / Kubell Lottery |
|---|---|
| Last available release: 2.60 | |

## Important Notes:

- Printers equipped with new memory components, can be correctly used only with FW release 2.60 or above

## Firmware changelog

| REL. | DATE | RELEASE NOTES |
|---|---|---|
| 2.60 | 01/Mar/22 | **Bug fixes and Improvements:**<br>• Improved QRCode management to print more dense symbols.<br>• Fixed an issue relative to 14x24 text positioning in bold.<br>• Now the printer tries to restore the cutter position when the Feed button is pressed in case of cutter error.<br>• Fixed bitimage print command ESC v<br>• Introduced new memory component support<br>• Fixed header information transmission to PrinterSet<br><br>**New Features:**<br>• Added new codepages in font Module 1.14 PC1257, PC720, PC864, PC1098, PC1256<br>• Created PFW file containing both firmware and font modules. |
| 2.38 | 13/May/16 | **Bug fixes and Improvements:**<br>• Fixed logo printing commands FS q and FS p<br>• Improvements to support new 2.23 Windows Driver package |
| 2.33 | 27/Oct/15 | **New Features:**<br>• Added QRCode printing capability. |
| 2.21 | 29/Jan/15 | **Bug fixes and Improvements:**<br>• Fixed different small issues in codepages and characters management.<br>• Support to firmware upgrade via PrinterSet tool.<br>• Removed unsupported RS232 Baud Rate options from PrinterSet dropdown menu.<br>• Fixed KU42 codepage management.<br>• Removed Logo2 management which is not available.<br>• Fixed ITF barcode printing.<br>• Fixed Bitimage print in PageMode<br>• Fixed PSW file to make it not editable via FontMake and LogoMake softwares.<br><br>**New Features:**<br>• Added CP855 codepage |
| 2.13 | 12/Dec/14 | **Bug fixes and Improvements:**<br>• Fixed an issue in font memory initialization.<br>• Introduced .MOD file management via PrinterSet for font module upgrade.<br>• Improved printer setup ticket header with firmware and font module codes.<br><br>**New Features:**<br>• Introduced Windows CE Compatibility over USB.<br>• Introduced Korean CP949 codetable<br>• Introduced CPT (Custom Power Tool) support. |
| 2.07 | 29/Set/14 | **New Features:**<br>• Introduced status monitor capability on USB interface0. |

**CUSTOM**®

| 2.06 | 17/Lug/14 | **Bug fixes and Improvements:**<br>• Major release digit increased to 2. Corresponding to HW release increment from R5 to R6. |
| 1.04 | 23/Apr/14 | **Bug fixes and Improvements:**<br>• First firmware release for KubeII and KubeLII with extended flash memory. |

**Additional Notes:**